# Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

| Checklist Reference Number | 200402                   |
|----------------------------|--------------------------|
| Date                       | 02 April 2020 (Thursday) |
| Time                       | 09:30 - 11:15            |

| Ref. No. | Non-Compliance  | Related<br>Item No. |
|----------|-----------------|---------------------|
| -        | None identified | -                   |

| Ref. No.  | Remarks/Observations  | Related<br>Item No. |
|---|---|---------------------|
| 200402 - R4   | <ul><li>B. Water Quality</li><li>It is observed that muddy runoff was discharged to the nearby waterbody. Berm or spill kit should be provided to prevent such accidence.</li></ul>   | <i>B2</i>           |
|   | <ul><li><i>C. Air Quality</i></li><li>No environmental deficiency was identified during site inspection.</li></ul>  |                     |
|   | <ul><li><i>D. Construction Noise Impact</i></li><li>No environmental deficiency was identified during site inspection.</li></ul>  |                     |
| 200402 - R1   | <ul> <li><i>E. Waste/Chemical Management</i></li> <li>A hole is found on the drip trap. Contractor is reminded that drip tray should be provided with well maintained.</li> </ul>   | <i>E9</i>           |
| $\begin{array}{c} 200402-R2 \\ 200402-R3 \end{array}$ | <ul> <li>Oil spill is observed near the drip tray. Oil leakage from the equipment should be avoided.</li> <li>Oil bottle without a suitable storage area is found.</li> </ul>   | E8<br>E3iii         |
|   | <ul><li><i>F. Visual and Landscape</i></li><li>No environmental deficiency was identified during site inspection.</li></ul>   |                     |
|   | <ul><li><i>G. Permits/Licences</i></li><li>No environmental deficiency was identified during site inspection.</li></ul>   |                     |
|   | <ul><li><i>H. Marine Ecology</i></li><li>No environmental deficiency was identified during site inspection.</li></ul>   |                     |
|   | <ul> <li><i>I. Others</i></li> <li>Follow-up on previous audit session (Ref No.:200326), follow-up actions are needed to be reviewed for items 200320 – R1&amp; 200320 – R2. Items 200320 – R3 has been rectified.</li> </ul> |                     |

|             | Name        | Signature | Date         |
|-------------|-------------|-----------|--------------|
| Recorded by | Tim Lui     | Cyli      | 3 April 2020 |
| Checked by  | Karina Chan | Jull      | 3 April 2020 |

# Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

| Checklist Reference Number | 200409                   |
|----------------------------|--------------------------|
| Date                       | 09 April 2020 (Thursday) |
| Time                       | 15:00 - 16:00            |

| F | Ref. No. | Non-Compliance  | Related<br>Item No. |
|---|----------|-----------------|---------------------|
|   | -        | None identified | -                   |

| Ref. No.    | Remarks/Observations   | Related<br>Item No. |
|-------------|--|---------------------|
|             | B. Water Quality   |                     |
| 200409 - R1 | • In launching shaft area, the excavated dusty materials should be covered by imperious materials. | B5                  |
|             | C. Air Quality   |                     |
|             | <ul> <li>No environmental deficiency was identified during site inspection.</li> </ul>             |                     |
|             | • No environmental denciency was identified during site inspection.                                |                     |
|             | D. Construction Noise Impact   |                     |
|             | • No environmental deficiency was identified during site inspection.                               |                     |
|             |  |                     |
|             | E. Waste/Chemical Management   |                     |
|             | • No environmental deficiency was identified during site inspection.                               |                     |
|             |  |                     |
|             | F. Visual and Landscape  |                     |
|             | • No environmental deficiency was identified during site inspection.                               |                     |
|             |  |                     |
|             | G. Permits/Licences  |                     |
|             | No environmental deficiency was identified during site inspection.                                 |                     |
|             | H. Marine Ecology  |                     |
|             | <ul> <li>No environmental deficiency was identified during site inspection.</li> </ul>             |                     |
|             | • No environmental deficiency was identified during site inspection.                               |                     |
|             | I. Others  |                     |
|             | • Follow-up on previous audit sessions (Ref No.:200320, 200402), all items has been rectified.     |                     |

|             | Name        | Signature | Date          |
|-------------|-------------|-----------|---------------|
| Recorded by | Tim Lui     | Cyli      | 14 April 2020 |
| Checked by  | Karina Chan | Zalle     | 14 April 2020 |

### Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

# Weekly Site Inspection Record Summary Inspection Information Checklist Reference Number 200416 Date 16 April 2020 (Thursday) Time 09:30 - 10:30

| Ref. No. | Non-Compliance  | Related<br>Item No. |
|----------|-----------------|---------------------|
| -        | None identified | -                   |

| Ref. No. | Remarks/Observations  | Related<br>Item No |
|----------|---|--------------------|
|          | B. Water Quality  |                    |
|          | • No environmental deficiency was identified during site inspection.                  |                    |
|          | C. Air Quality  |                    |
|          | • No environmental deficiency was identified during site inspection.                  |                    |
|          | D. Construction Noise Impact  |                    |
|          | • No environmental deficiency was identified during site inspection.                  |                    |
|          | E. Waste/Chemical Management  |                    |
|          | • No environmental deficiency was identified during site inspection.                  |                    |
|          | F. Visual and Landscape   |                    |
|          | • No environmental deficiency was identified during site inspection.                  |                    |
|          | G. Permits/Licences   |                    |
|          | • No environmental deficiency was identified during site inspection.                  |                    |
|          | H. Marine Ecology   |                    |
|          | • No environmental deficiency was identified during site inspection.                  |                    |
|          | I. Others   |                    |
|          | • Follow-up on previous audit session (Ref No.:200409), all items has been rectified. |                    |

|             | Name        | Signature | Date          |
|-------------|-------------|-----------|---------------|
| Recorded by | Tim Lui     | Cyli      | 17 April 2020 |
| Checked by  | Karina Chan | Julle     | 17 April 2020 |

# Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

| Checklist Reference Number | 200423                   |
|----------------------------|--------------------------|
| Date                       | 23 April 2020 (Thursday) |
| Time                       | 09:30 - 11:30            |

| Ref. No. | Non-Compliance  | Related<br>Item No. |
|----------|-----------------|---------------------|
| -        | None identified | -                   |

| Ref. No.    | Remarks/Observations   | Related<br>Item No. |
|-------------|--|---------------------|
|             | <ul> <li>B. Water Quality</li> <li>No environmental deficiency was identified during site inspection.</li> </ul>                         |                     |
| 200423 - R1 | <ul><li><i>C. Air Quality</i></li><li>Dump trunk exit from the mud pit area without using the wheel wash facility is observed.</li></ul> | C10                 |
|             | <ul> <li>D. Construction Noise Impact</li> <li>No environmental deficiency was identified during site inspection.</li> </ul>             |                     |
|             | <ul><li><i>E. Waste/Chemical Management</i></li><li>No environmental deficiency was identified during site inspection.</li></ul>         |                     |
|             | <ul><li><i>F. Visual and Landscape</i></li><li>No environmental deficiency was identified during site inspection.</li></ul>              |                     |
|             | <ul><li><i>G. Permits/Licences</i></li><li>No environmental deficiency was identified during site inspection.</li></ul>                  |                     |
|             | <ul><li><i>H. Marine Ecology</i></li><li>No environmental deficiency was identified during site inspection.</li></ul>                    |                     |
|             | <ul><li><i>I. Others</i></li><li>Follow-up on previous audit session (Ref No.:200409), all items has been rectified.</li></ul>           |                     |

|             | Name        | Signature | Date          |
|-------------|-------------|-----------|---------------|
| Recorded by | Tim Lui     | Cyli      | 24 April 2020 |
| Checked by  | Karina Chan | Julle     | 24 April 2020 |

# Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

| Checklist Reference Number | 200429                    |  |
|----------------------------|---------------------------|--|
| Date                       | 29 April 2020 (Wednesday) |  |
| Time                       | 09:30 - 11:30             |  |

| Ref. No. | Non-Compliance  | Related<br>Item No. |
|----------|-----------------|---------------------|
| -        | None identified | -                   |

| Ref. No.    | Remarks/Observations  | Related<br>Item No. |
|-------------|---|---------------------|
|             | <ul><li><i>B. Water Quality</i></li><li>No environmental deficiency was identified during site inspection.</li></ul>                                      |                     |
| 200429 - R1 | <ul><li><i>C. Air Quality</i></li><li>Watering should be provided 12 times per day to avoid dust generation.</li></ul>                                    | C1                  |
|             | <ul> <li><i>D. Construction Noise Impact</i></li> <li>No environmental deficiency was identified during site inspection.</li> </ul>                       |                     |
|             | <ul> <li><i>E. Waste/Chemical Management</i></li> <li>No environmental deficiency was identified during site inspection.</li> </ul>                       |                     |
|             | <ul> <li>F. Visual and Landscape</li> <li>No environmental deficiency was identified by Registered Landscape Architect during site inspection.</li> </ul> |                     |
|             | <ul><li><i>G. Permits/Licences</i></li><li>No environmental deficiency was identified during site inspection.</li></ul>                                   |                     |
|             | <ul><li><i>H. Marine Ecology</i></li><li>No environmental deficiency was identified during site inspection.</li></ul>                                     |                     |
|             | <ul><li><i>I. Others</i></li><li>Follow-up on previous audit session (Ref No.:200423), all items has been rectified.</li></ul>                            |                     |

|             | Name        | Signature | Date       |
|-------------|-------------|-----------|------------|
| Recorded by | Tim Lui     | Cyli      | 4 May 2020 |
| Checked by  | Karina Chan | Jull      | 4 May 2020 |