Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	200702
Date	02 July 2020 (Thursday)
Time	09:30 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
200702 - O1	Air compressor operate with door opened is observed.	D9
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	W. W. Co. F. J.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow-up on previous audit session (Ref No.:200623), all item has been rectified.	

	Name	Signature	Date
Recorded by	Tim Lui	Cyli	02 July 2020
Checked by	Karina Chan	Zall	02 July 2020

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	200709
Date	09 July 2020 (Thursday)
Time	09:30 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow-up on previous audit session (Ref No.:200702), all item has been rectified.	

	Name	Signature	Date
Recorded by	Tim Lui	Cyli	10 July 2020
Checked by	Karina Chan	Zall	10 July 2020

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	200716
Date	16 July 2020 (Thursday)
Time	09:30 – 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
200716 – R1	 B. Water Quality Manhole in which located nearby the site entrance are likely to be contaminated by muddy water generated from site. Contractor was reminded to seal on /around the manhole to prevent the muddy water flowing through it. C. Air Quality No environmental deficiency was identified during site inspection. 	В8
	 D. Construction Noise Impact No environmental deficiency was identified during site inspection. 	
	 E. Waste/Chemical Management No environmental deficiency was identified during site inspection. 	
	 F. Visual and Landscape No environmental deficiency was identified during site inspection. 	
	 G. Permits/Licences No environmental deficiency was identified during site inspection. 	
	 H. Marine Ecology No environmental deficiency was identified during site inspection. 	
	 I. Others No environmental deficiency was identified on previous audit session (Ref No.:200709), 	

	Name	Signature	Date
Recorded by	Tim Lui	Cyli	17 July 2020
Checked by	Karina Chan	Zalle	17 July 2020

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	200723
Date	23 July 2020 (Thursday)
Time	09:30 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality No environmental deficiency was identified during site inspection.	
200723 – R2	C. Air Quality Watering regularly within the work area enclosed by the blast door was recommended to avoided dust generation.	C1, C15
200723 - R1	 D. Construction Noise Impact Moveable noise barrier shall be provided to reduce the noise nuisance generated from the breaker. 	D7
	 E. Waste/Chemical Management No environmental deficiency was identified during site inspection. 	
	 F. Visual and Landscape No environmental deficiency was identified during site inspection. 	
	 G. Permits/Licences No environmental deficiency was identified during site inspection. 	
	 H. Marine Ecology No environmental deficiency was identified during site inspection. 	
	 I. Others Follow-up on previous audit session (Ref No.:200716), all item has been rectified. 	

	Name	Signature	Date
Recorded by	Tim Lui	Cyli	24 July 2020
Checked by	Karina Chan	Zalle	24 July 2020

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	200730	
Date	30 July 2020 (Thursday)	
Time	09:30 – 12:00	

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
200730 - R1	Still water was observed near the Bar Bending Yard.	В9
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	• No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow-up on previous audit session (Ref No.:200730), item (200723 – R2) has been rectified and the follow-up action are required for item (200723 – R1).	

	Name	Signature	Date
Recorded by	Tim Lui	Cyli	31 July 2020
Checked by	Karina Chan	Zalle	31 July 2020