Contract No. ED/2018/04 Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron Quarterly EM&A Report

Appendix F - Site Audit Summary

<u>May 2020</u>

Items	Date	Status*	Follow up Action		
Water Quality					
Water pond was found at the site. Drainage system should be adequately designed for storm flow.	21 May 2020	~	Item was rectified on 28 May 2020.		
Ecology	-				
Noise					
Landscape and Visual					
Existing tree to be retained on site should be protected carefully.	21 May 2020	#	Follow up action will be reported in the next reporting month.		
Air Quality					
Waste / Chemical Management					
Impact on Cultural Heritage					
Permits / Licenses					

✔ Observation/reminder was made during site audit but improved/rectified by the contractor in the next site audit

* Observation/reminder was made during site audit but not yet improved/rectified by the contractor in the next site audit

Follow up action will be reported in next reporting month

* Non-compliance of mitigation measure

• Non-compliance but improved by the contractor

Contract No. ED/2018/04 Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron Quarterly EM&A Report

Appendix F - Site Audit Summary

June 2020

Items	Date	Status*	Follow up Action			
Water Quality						
Noise						
Mitigation measure for construction noise reduction, as listed in the NMP (v.3), should be implemented on CKL site	11 June 2020	~	Improved/rectified on 23 June 2020			
Landscape and Visual						
Existing tree to be retained on site should be protected carefully.	21 May 2020	~	Improved/rectified on 04 June 2020			
Air Quality						
Waste / Chemical Management						
Impact on Cultural Heritage						
Permits / Licenses						

✔ Observation/reminder was made during site audit but improved/rectified by the contractor in the next site audit

X Observation/reminder was made during site audit but not yet improved/rectified by the contractor in the next site audit

Follow up action will be reported in next reporting month

* Non-compliance of mitigation measure

• Non-compliance but rectified by the contractor

Contract No. ED/2018/04 Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron Quarterly EM&A Report

Appendix F - Site Audit Summary

July 2020

Items	Date	Status*	Follow up Action		
Water Quality					
Noise					
Moveable noise barrier shall be provided to reduce the noise nuisance generated from breaker.	23 July 2020	#	Follow up action will be reported in the next reporting month.		
Landscape and Visual					
Air Quality					
Watering regularly within the work area enclosed by the blast door was recommended to avoided dust generation.	23 July 2020	v	Improved/rectified on 30 July 2020		
Waste / Chemical Management					
Impact on Cultural Heritage					
Permits / Licenses					

✔ Observation/reminder was made during site audit but improved/rectified by the contractor in the next site audit

* Observation/reminder was made during site audit but not yet improved/rectified by the contractor in the next site audit

Follow up action will be reported in next reporting month

* Non-compliance of mitigation measure

• Non-compliance but rectified by the contractor