Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

| Checklist Reference Number | 250403 |
|----------------------------|--------------------------|
| Date | 03 April 2025 (Thursday) |
| Time | 09:30 – 16:30 |

| Ref. No. | Non-Compliance | Related Item No. |
|----------|-----------------|---------------------|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|----------|---|---------------------|
| | B. Water Quality | |
| | No environmental deficiency was identified during site inspection. | |
| | C. Air Quality | |
| | No environmental deficiency was identified during site inspection. | |
| | D. Construction Noise Impact | |
| | No environmental deficiency was identified during site inspection. | |
| | E. Waste/Chemical Management | |
| | No environmental deficiency was identified during site inspection. | |
| | F. Visual and Landscape | |
| | No environmental deficiency was identified during site inspection. | |
| | G. Permits/Licences | |
| | No environmental deficiency was identified during site inspection. | |
| | H. Marine Ecology | |
| | No environmental deficiency was identified during site inspection. | |
| | I Oth | |
| | I. Others No environmental deficiency was identified in provious session (Ref No : 250227) | |
| | • No environmental deficiency was identified in previous session (Ref No.: 250327). | |

| | Name | Signature | Date |
|-------------|---------------|-----------|---------------|
| Recorded by | William Yeung | K | 03 April 2025 |
| Checked by | Karina Chan | Zalle | 07 April 2025 |

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

| Checklist Reference Number | 250410 |
|----------------------------|--------------------------|
| Date | 10 April 2025 (Thursday) |
| Time | 09:30 – 16:30 |

| Ref. No. | Non-Compliance | Related Item No. |
|----------|-----------------|---------------------|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|----------|---|---------------------|
| | B. Water Quality | |
| | No environmental deficiency was identified during site inspection. | |
| | C. Air Quality | |
| | No environmental deficiency was identified during site inspection. | |
| | D. Construction Noise Impact | |
| | • No environmental deficiency was identified during site inspection. | |
| | E. Waste/Chemical Management | |
| | No environmental deficiency was identified during site inspection. | |
| | F. Visual and Landscape | |
| | No environmental deficiency was identified during site inspection. | |
| | G. Permits/Licences | |
| | No environmental deficiency was identified during site inspection. | |
| | H. Marine Ecology | |
| | No environmental deficiency was identified during site inspection. | |
| | I. Others | |
| | • No environmental deficiency was identified in previous session (Ref No.: 250403). | |

| | Name | Signature | Date |
|-------------|---------------|-----------|---------------|
| Recorded by | William Yeung | B | 10 April 2025 |
| Checked by | Karina Chan | Zalle | 14 April 2025 |

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

| Checklist Reference Number | 250417 |
|----------------------------|--------------------------|
| Date | 17 April 2025 (Thursday) |
| Time | 09:30 – 16:30 |

| Ref. No. | Non-Compliance | Related Item No. |
|----------|-----------------|---------------------|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|----------|---|---------------------|
| | B. Water Quality | |
| | No environmental deficiency was identified during site inspection. | |
| | C. Air Quality | |
| | No environmental deficiency was identified during site inspection. | |
| | D. Construction Noise Impact | |
| | No environmental deficiency was identified during site inspection. | |
| | E. Waste/Chemical Management | |
| | No environmental deficiency was identified during site inspection. | |
| | F. Visual and Landscape | |
| | No environmental deficiency was identified during site inspection. | |
| | G. Permits/Licences | |
| | No environmental deficiency was identified during site inspection. | |
| | H. Marine Ecology | |
| | No environmental deficiency was identified during site inspection. | |
| | I. Others | |
| | • No environmental deficiency was identified in previous session (Ref No.: 250410). | |

| | Name | Signature | Date |
|-------------|---------------|-----------|---------------|
| Recorded by | William Yeung | B | 17 April 2025 |
| Checked by | Karina Chan | Zalle | 22 April 2025 |

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

| Checklist Reference Number | 250424 |
|----------------------------|--------------------------|
| Date | 24 April 2025 (Thursday) |
| Time | 09:30 – 16:30 |

| Ref. No. | Non-Compliance | |
|----------|-----------------|---|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|----------|--|---------------------|
| | B. Water Quality No environmental deficiency was identified during site inspection. | |
| | C. Air Quality No environmental deficiency was identified during site inspection. D. Construction Noise Impact No environmental deficiency was identified during site inspection. | |
| | E. Waste/Chemical Management No environmental deficiency was identified during site inspection. | |
| | F. Visual and Landscape No environmental deficiency was identified during site inspection. | |
| | G. Permits/Licences No environmental deficiency was identified during site inspection. | |
| | H. Marine Ecology No environmental deficiency was identified during site inspection. | |
| | I. Others No environmental deficiency was identified in previous session (Ref No.: 250417). | |

| | Name | Signature | Date |
|-------------|---------------|-----------|---------------|
| Recorded by | William Yeung | | 24 April 2025 |
| Checked by | Karina Chan | Jalle | 28 April 2025 |

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

| Checklist Reference Number | 250430 |
|----------------------------|---------------------------|
| Date | 30 April 2025 (Wednesday) |
| Time | 09:30 – 16:30 |

| Ref. No. | Non-Compliance | |
|----------|-----------------|---|
| - | None identified | - |

| Ref. No. | Remarks/Observations | Related Item No. |
|--|--|---------------------|
| | B. Water Quality | |
| 250430-458-R1 | Stagnant water was observed. | B09 |
| | C. Air Quality | |
| | No environmental deficiency was identified during site inspection. | |
| | D. Construction Noise Impact | |
| | No environmental deficiency was identified during site inspection. | |
| | E. Waste/Chemical Management | |
| | No environmental deficiency was identified during site inspection. | |
| | F. Visual and Landscape | |
| | No environmental deficiency was identified during site inspection. | |
| | G. Permits/Licences | |
| | No environmental deficiency was identified during site inspection. | |
| | H. Marine Ecology | |
| | No environmental deficiency was identified during site inspection. | |
| | I Odlam | |
| | I. Others | |
| No environmental deficiency was identified in previous session (Ref No.: 1 | | 1 |

| | Name | Signature | Date |
|-------------|---------------|-----------|---------------|
| Recorded by | William Yeung | B | 30 April 2025 |
| Checked by | Karina Chan | Zoll | 2 May 2025 |