

**Contract No. ED/2018/04**

**Environmental Team for Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron**



**Weekly Site Inspection Record Summary**

**Inspection Information**

Checklist Reference Number	200320
Date	20 March 2020 (Friday)
Time	10:00 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
200320 – R1 200320 – R2	<b>B. Water Quality</b> <ul style="list-style-type: none"><li>Wheel washing bay should be provided at every site exit.</li><li>Sediment tank should be provided for settling the muddy water prior to discharge.</li></ul>	<i>B11i</i> <i>B4i</i>
200320 – R1	<b>C. Air Quality</b> <ul style="list-style-type: none"><li>Wheel washing bay should be provided at every site exit.</li></ul>	<i>C10</i>
200320 – R3	<b>D. Construction Noise Impact</b> <ul style="list-style-type: none"><li>PME should be shielded by appropriate material.</li></ul>	<i>D5</i>
	<b>E. Waste/Chemical Management</b> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul>	
	<b>F. Visual and Landscape</b> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul>	
	<b>G. Permits/Licences</b> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul>	
	<b>H. Marine Ecology</b> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul>	
	<b>I. Others</b> <ul style="list-style-type: none"><li>N/A</li></ul>	

	Name	Signature	Date
Recorded by	Tim Lui		21 March 2020
Checked by	Karina Chan		21 March 2020

**Contract No. ED/2018/04**

**Environmental Team for Trunk Road T2 and Infrastructure Works for Developments at the Former South Apron**



**Weekly Site Inspection Record Summary**

**Inspection Information**

Checklist Reference Number	200326
Date	26 March 2020 (Thursday)
Time	09:30 - 11:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	<p><b>B. Water Quality</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>C. Air Quality</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>D. Construction Noise Impact</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>E. Waste/Chemical Management</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>F. Visual and Landscape</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>G. Permits/Licences</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>H. Marine Ecology</b></p> <ul style="list-style-type: none"><li>No environmental deficiency was identified during site inspection.</li></ul> <p><b>I. Others</b></p> <ul style="list-style-type: none"><li>Follow-up on previous audit session (Ref No.:200320), follow-up actions are needed to be reviewed for items 200320 – R1, 200320 – R2 &amp; 200320 – R3.</li></ul>	

	Name	Signature	Date
Recorded by	Tim Lui		26 March 2020
Checked by	Karina Chan		26 March 2020