

Appendix H - Noise Monitoring Results



Location CKL1 - Flat 121 Cha Kwo Ling Village

Date	Time	Weather	Unit: dB (A) (30-min)				
			Measured Noise Level			Baseline Level	Construction Noise Level
			L _{eq}	L ₁₀	L ₉₀	L _{eq}	L _{eq}
2-Jul-20	10:00	Sunny	69.9	73.0	60.1	72.4	69.9 Measured ≤ Baseline
8-Jul-20	16:00	Fine	68.6	72.3	59.9	72.4	68.6 Measured ≤ Baseline
14-Jul-20	13:00	Sunny	68.4	71.9	59.9	72.4	68.4 Measured ≤ Baseline
20-Jul-20	16:00	Fine	69.7	73.4	57.6	72.4	69.7 Measured ≤ Baseline
30-Jul-20	9:30	Sunny	67.5	71.5	59.6	72.4	67.5 Measured ≤ Baseline

Location CKL2 - Flat 103 Cha Kwo Ling Village

Date	Time	Weather	Unit: dB (A) (30-min)				
			Measured Noise Level			Baseline Level	Construction Noise Level
			L _{eq}	L ₁₀	L ₉₀	L _{eq}	L _{eq}
2-Jul-20	9:25	Sunny	67.9	70.9	60.0	71.4	67.9 Measured ≤ Baseline
8-Jul-20	16:40	Fine	69.9	72.3	62.7	71.4	69.9 Measured ≤ Baseline
14-Jul-20	14:00	Sunny	67.7	71.6	58.9	71.4	67.7 Measured ≤ Baseline
20-Jul-20	16:40	Fine	68.4	71.6	56.3	71.4	68.4 Measured ≤ Baseline
30-Jul-20	10:30	Sunny	68.8	72.4	59.7	71.4	68.8 Measured ≤ Baseline

Noise Levels



Title Kai Tak Development – Trunk Road T2 and Infrastructure Works at the Former South Apron Graphical Presentation of Construction Noise Monitoring Results	Date	Project	CINOTECH
	July 20	No. MA20003	
		Appendix H	