

## Appendix H - Noise Monitoring Results

### Location CKL1 - Flat 121 Cha Kwo Ling Village

Date	Time	Weather	Unit: dB (A) (30-min)				Construction Noise Level
			Measured Noise Level			Baseline Level	
			L <sub>eq</sub>	L <sub>10</sub>	L <sub>90</sub>	L <sub>eq</sub>	
4-Aug-20	9:10	Rainy	72.5	75.1	64.2	72.4	56
10-Aug-20	10:05	Sunny	72.9	75.2	62.9	72.4	63
20-Aug-20	10:10	Sunny	70.9	74.0	64.3	72.4	70.9 Measured ≤ Baseline
26-Aug-20	10:00	Sunny	71.5	74.7	63.4	72.4	71.5 Measured ≤ Baseline

### Location CKL2 - Flat 103 Cha Kwo Ling Village

Date	Time	Weather	Unit: dB (A) (30-min)				Construction Noise Level
			Measured Noise Level			Baseline Level	
			L <sub>eq</sub>	L <sub>10</sub>	L <sub>90</sub>	L <sub>eq</sub>	
4-Aug-20	9:45	Rainy	71.7	74.8	65.3	71.4	59.9
10-Aug-20	10:35	Sunny	68.8	72.2	62.0	71.4	68.8 Measured ≤ Baseline
20-Aug-20	10:50	Sunny	68.4	72.1	59.1	71.4	68.4 Measured ≤ Baseline
26-Aug-20	10:45	Sunny	70.5	74.3	61.1	71.4	70.5 Measured ≤ Baseline



## Appendix H - Noise Monitoring Results

Location KTD1 - Centre of Excellence in Paediatrics (Rooftop of Children's Hospital)							
Date	Time	Weather	Unit: dB (A) (30-min)				
			Measured Noise Level			Baseline Level	Construction Noise Level
			L <sub>eq</sub>	L <sub>10</sub>	L <sub>90</sub>	L <sub>eq</sub>	L <sub>eq</sub>
4-Aug-20	10:33	Rainy	66.2	68.4	65.5	78.0	66.2 Measured ≤ Baseline
10-Aug-20	11:30	Sunny	66.6	67.3	66.4	78.0	66.6 Measured ≤ Baseline
20-Aug-20	14:47	Sunny	68.6	69.8	67.2	78.0	68.6 Measured ≤ Baseline
26-Aug-20	17:01	Sunny	73.2	74.6	71.5	78.0	73.2 Measured ≤ Baseline

Location KTD2c - G/C Zone next to Kwun Tong Bypass (Next to the Kowloon Bay Sewage Interception Station)							
Date	Time	Weather	Unit: dB (A) (30-min)				
			Measured Noise Level			Baseline Level	Construction Noise Level
			L <sub>eq</sub>	L <sub>10</sub>	L <sub>90</sub>	L <sub>eq</sub>	L <sub>eq</sub>
4-Aug-20	1:00	Rainy	71.4	74.8	67.2	64.0	71
10-Aug-20	14:30	Sunny	72.2	75.0	68.2	64.0	71
20-Aug-20	10:57	Sunny	72.4	73.8	70.0	64.0	72
26-Aug-20	16:25	Sunny	70.4	71.9	66.1	64.0	69




Location KER1 - Future Residential Development at Kerry Godown							
Date	Time	Weather	Unit: dB (A) (30-min)				
			Measured Noise Level			Baseline Level	Construction Noise Level
			L <sub>eq</sub>	L <sub>10</sub>	L <sub>90</sub>	L <sub>eq</sub>	L <sub>eq</sub>
4-Aug-20	14:20	Rainy	74.1	74.9	73.1	65.0	74
10-Aug-20	15:15	Sunny	72.7	74.5	70.1	65.0	72
20-Aug-20	15:32	Sunny	69.5	70.4	67.7	65.0	68
26-Aug-20	15:29	Sunny	70.8	71.7	69.4	65.0	69

## Noise Levels



Title Kai Tak Development – Trunk Road T2 and Infrastructure Works at the Former South Apron  Graphical Presentation of Construction Noise Monitoring Results	Date	Project	CINOTECH
	Aug 20	No. MA20003	
		Appendix H	

## Noise Levels



Title Kai Tak Development – Trunk Road T2 and Infrastructure Works at the Former South Apron  Graphical Presentation of Construction Noise Monitoring Results	Date	Project	CINOTECH
	Aug 20	No. MA20003 Appendix H	