## Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	210901
Date	01 September 2021 (Wednesday)
Time	09:30 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No
	B. Water Quality	
	No environmental deficiency was identified during site inspection	
	C. Air Quality	
	No environmental deficiency was identified during site inspection	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:210826), all item has been rectified.	

	Name	Signature	Date
Recorded by	Tim Lui	Cyli	01 September 2021
Checked by	Karina Chan	Zelle	01 September 2021

## Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	210909
Date	09 September 2021 (Thursday)
Time	09:30 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection	
	C. Air Quality	
	No environmental deficiency was identified during site inspection	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:210901), no major environmental deficiency was identified.	

	Name	Signature	Date
Recorded by	Tim Lui	Cyli	09 September 2021
Checked by	Karina Chan	Jeffer	09 September 2021

## Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	210917
Date	17 September 2021 (Friday)
Time	09:30 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection	
	C. Air Quality	
	No environmental deficiency was identified during site inspection	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:210909), no major environmental deficiency was identified.	

	Name	Signature	Date
Recorded by	Tim Lui	Cyli	17 September 2021
Checked by	Karina Chan	Jeffer	17 September 2021

## Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	210923
Date	23 September 2021 (Thursday)
Time	09:30 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection	
	C. Air Quality	
	No environmental deficiency was identified during site inspection	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:210917), no major environmental deficiency was identified.	

	Name	Signature	Date
Recorded by	Tim Lui	Cyli	23 September 2021
Checked by	Karina Chan	Zelle	23 September 2021

## Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	210930
Date	30 September 2021 (Thursday)
Time	09:30 – 12:00

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality     No environmental deficiency was identified during site inspection	
	<ul> <li>C. Air Quality</li> <li>No environmental deficiency was identified during site inspection</li> </ul>	
210930 – R1	<ul> <li>D. Construction Noise Impact</li> <li>Contractor was reminded to check on the effectiveness of the implemented noise mitigation measure regularly. Noise barriers should be erected to block the direct view of noise source from NSR.</li> </ul>	D7
	<ul> <li>E. Waste/Chemical Management</li> <li>No environmental deficiency was identified during site inspection.</li> </ul>	
	<ul> <li>F. Visual and Landscape</li> <li>No environmental deficiency was identified during site inspection.</li> </ul>	
	<ul> <li>G. Permits/Licences</li> <li>No environmental deficiency was identified during site inspection.</li> </ul>	
	<ul> <li>H. Marine Ecology</li> <li>No environmental deficiency was identified during site inspection.</li> </ul>	
	<ul> <li>I. Others</li> <li>Follow up on the previous session (Ref No.:210927), no major environmental deficiency was identified.</li> </ul>	

	Name	Signature	Date
Recorded by	Tim Lui	Cyli	30 September 2021
Checked by	Karina Chan	Jalle	30 September 2021